



2400 Wilson Place
P.O. Box 6110
Temple, Texas 76503-6110

Wilsonart® Decorative Metals Care & Maintenance

Clean anodized aluminum surfaces with warm water and mild soaps such as those used for hands or 409® Glass & Surface Cleaner and warm water with a mild soap such as those used for hands or dishes. Household cleaners, non-ammoniated detergents, or glass cleaners may be used. Stubborn stains may be removed with a thin, clean oil and a dry cloth. After cleaning, always wipe the surface completely dry with a soft, clean cloth.

Do NOT use cleaners that contain abrasives, acids or alkalis, as they will mar the surface. Ammoniated detergents or petroleum-based cleaners should not be used to clean anodized aluminum surfaces.

Do NOT clean metal face with solvents, paint thinner or adhesive remover.